Original user manual

Soft Brush





1. Declaration of Conformity

EU Declaration of Conformity

Manufacturer: Jasopels A/S Tel. +45 76 94 35 00

Address: Fabriksvej 19 DK-7441 Bording

Machine: Soft Brush
Type: 53-0000

Jasopels A/S declares that this product is in accordance with the following EU Directives:

2006/42/EC

2006/95/EC

2006/108/EC

Furthermore, we declare that relevant chapters of the following harmonized standards have been applied:

EN 60204-1

DS/EN 12100: 2005

DS/EN 14121-1

DS/EN 14121-2

DS/EN 13857: 2008

DS/EN 13850

Place and date: Bording, January 31, 2012

Name: CEO Poul Bach

(AntBack



2. Table of contents

1.	Declaration of Conformity	2
2.	Table of contents	3
3.	Preface	4
4.	Symbol explanation	5
5.	Introduction of the machine	6
6.	Start-up	7
7.	Operation	8
8.	Maintenance	9
9.	Technical data 1	12
10	Circuit diagram1	13
11.	Spare parts list 1	16
12	User's notes	18



3. Preface

- This User Manual is an important part of your new machine.
 Read the manual thoroughly and use it as a reference book.
- This manual contains important information about safety and the correct use of the machine.
- The manual should be stored with the machine. It is important that the user manual is supplied with the machine upon resale and lending.
- The owner of the machine must make sure that the operator, service personnel and others who have access to the machine have been instructed in the correct use and handling of the machine. Refer to this user manual for further information.
- Unauthorized modifications, additions or changes to are not allowed for the sake of overall safety. Neither the manufacturer nor the supplier can be held liable for damages incurred as a result of the above. All and any risks in the case of such misuse are the end user's alone.



4. Symbol explanation

Please read this user manual and follow the included instructions. In order to emphasize certain information, the following expressions are used:

• Note!



A triangle with an exclamation mark is a symbol that warns you of important instructions or information concerning this machine.

• Danger!



A triangle with a flash of lightning is a symbol that warns you of "High Voltage".

Warning!



A triangle warning you of entanglement and crush hazard.



5. Introduction of the machine

- The Jasopels Soft Brush is designed for softening mink skins.
- After being treated using the Soft Brush, the skins are soft and fluffy.
 They are ready to be delivered to the customer.
- The machine is simple and easy to use.

Note!

- Make sure to read the manual before using the machine.
- The owner of the machine must make sure that the operator, service personnel and others who have access to the machine are instructed on the proper use and handling of the machine.
- The machine may only be used for the purpose it is designed for. The CE Declaration becomes void upon any other use of the machine.
- If any problems occur with the machine or its operation, the machine must be properly shut off before the problem is fixed, unless the correction can be made using the machine's control keys.
- The user manual must always be kept available for the operator.





6. Start-up

- Before start-up the machine must be placed on a firm and level floor.
- The manufacturer has equipped the machine with a 5-pin 16 A CEE plug at the end of the power cable. The machine must be connected to an outlet with 3P+N+PE. An air connection has been installed by the electrical cabinet. It includes a filter and a water separator, where the compressed air hose from the compressor is to be connected.
- A suction device can be connected to the machine. This will remove loose hair and sawdust from the skin's outer side and prevent hair and sawdust from being thrown around the room.
- The Soft Brush is now ready to be used.

DANGER!

Always disconnect the machine's compressed air and electrical power supply before maintenance, cleaning and other service activities are performed on the machine.



In order to avoid potential damage to the control unit's microcontrollers and the rest of the machine's electrical system due to thunderstorms, it is recommended to disconnect the machine from its electrical power source whenever it is not being used.





7. Operation

After the Soft Brush has been correctly connected, it is ready to be used.

At the back of the machine there are to switches. The machine is started using the black one and switched off using the red one.



Fig. 1

When the machine is started the chain with the skin transporter runs continuously. The skin is put on one of the hooks with the back side facing out. After that it gets pulled through the machine from left to right and then pushed out of the machine.

After this treatment the skin is ready to be delivered to the customer!

DANGER!

Avoid putting your fingers into the machine's inlet and the area around the skin remover as this can lead to entanglement and crushing.





9. Maintenance

DANGER!

If you need to clean the machine or perform maintenance of it, the electrical power cable and the air-pressure supply hose <u>MUST</u> be disconnected before you begin.



8.1 Belt replacement

- Begin by removing the panel on the back side of the Soft Brush.
- After that you can remove the belt. The belt can be loosened/tightened using the oblong holes for the motor bracket.



Oblong holes for the motor

Fig. 2 Belt replacement

• The last step is putting the panel back on.



8.2 Tightening the chain



Fig. 3 Tightening the chain

 The bolts by the bearing housing need to be loosened. Tightening takes place from outside using the tightening bolt.

DANGER!

If you need to perform maintenance of the machine, the power cable and the air-pressure supply hose <u>MUST</u> be disconnected before you begin.





8.2 Brush replacement




Fig. 4 Brush replacement

The Soft Brush needs almost no maintenance but the brushes tend to suffer from normal wear and tear. When the brushes need to be replaced, proceed in the following way:

- Shut off and disconnect the power and air supply.
- Unscrew the screens.
- Each brush is fitted using 3 Allen bolts. Unscrew the 3 bolts, remove the old brush, put the new one in and fasten the 3 bolts again. Repeat this procedure for all brushes that need to be replaced.
- Screw the screens back on.
- Connect the air and power supply and resume work.
- At the end of the season the machine needs to be cleaned with compressed air. When the cleaning process is finished, all lubricant nipples on the bearings need to be lubricated.

Fig. number	Jaso number	Name
4.1	5190-00529000	Brush for skin cleaner 150 mm

DANGER!

If you need to perform maintenance of the machine, the power cable and the air-pressure supply hose <u>MUST</u> be disconnected before you begin.





9. Technical data

Electrical connection
 3 x 400 V + PE 5-pin CEE plug

• Energy consumption 16 A

Air connection Quick release coupling
 Air consumption Max. 8 bar 50 l/min


• Dimensions Height: 77 cm

Length: 235 cm


Width: 81 cm




10. Circuit diagram













12. Spare parts list




Fig. 5 Electrical cabinet

Fig. number	Jaso number	Description
5.1	5927-14080060	Component clamp
5.2	5925-14020030	B & J contactor K2-12A01-230V
5.3	5925-34022050	B & J thermo overload relay 1,2-1,8 A
5.4	5925-34022060	B & J thermo overload relay 1,8-2,7 A
5.5	5921-14000110	Microcontroller 1761-L16BWA
5.6	5911-300941616	Choker in-line RFL-R-B 6-6
5.7	5911-37062020105	MSV 25 SOP 00 220AC 5/2 EI/F
5.8	5914-32001010	Regulator MR bit 1/8 08 bar
5.9	5923-14002160	Inductive sensor Ø 12 PNP
5.10	5923-14002230	Inductive sensor Ø 18 PNP NO






Fig. 6 Brushes

Fig. number	Jaso number	Description
6.1	5190-00529000	Brush for skin cleaner 150 mm
6.2	5940-11200031	Guiding bracket Size 20
6.3	5912-34020075	Compact cylinder CMPC Ø20-0075
6.4	5967-0600081000	Roller chain 1/2"
6.5	5931-10037414	Brush motor
6.6	5931-10055403	Chain motor



12. User's notes